

## MHT-355 W

### Wireless Temperature and Humidity Indicators

#### Overview:

#### The outdoor temperature and indoor temperature/humidity survey method:

- \* Press MAX key, the values of highest temperature/humidity inside and temperature outside at present will be displayed.
- \* Press MIN key, the values of lowest temperature/humidity inside and temperature outside at present will be displayed.
- \* Press RESET key, the highest/lowest value will be re-set at present, and it will record the new values.

#### Features:

- \* 3 line of LCD display
- \* Show the outdoor temperature and indoor temperature/humidity at the same time.
- \* select °C or °F anytime by pushing the buttons on the back of the instrument.
- \* Recording the highest or lowest temperature/humidity value every day.
- \* the instrument has one string to deduct location behind one's back and prop up the board, can hang on the wall or put on the desk

#### Temperature survey range:

Outdoor: 0°C to 50°C

Indoor: 0°C to 50°C

Analyze degree: 0.1°C

Accurate precision: ±1°C

Humidity survey range: 10%RH to 98%RH

Analyze degree: 1%RH

Accurate precision: ±5%RH

